

## 跳线如何解决

### How to solve the problem of missing stitch

<p>跳线如何解决 How to solve the problem of missing stitch</p>	
<p>启动刹车按钮 Press the brake button</p>	
<p>然后 主轴往逆时针方向转动 Rotate the main shaft until the needle comes to the lowest position</p>	

## 跳线如何解决

### How to solve the problem of missing stitch

转动后 开始重新调节针和钩子间的位置  
Readjust the position between the needle and the  
looper hook



调好之后，机器已正常运行  
After adjusting, The machine is running normally

